PRODUCT CHANGE NOTIFICATION

HR2280-BT

Product part number: HR2280-BTV2-SF

Bluetooth Handheld Scanner with BT dongle

Reason for change

Upgrade the 2.4G dongle to Bluetooth 5.0 Dongle to improve the communication distance and stability.

Summary of changes

Model Changes:

▎ From HR2280-BT-SF to HR2280-BTV2-SF

Hardware Changes:

▎ The Bluetooth dongle included in the kit has changed from a Bluetooth HID 2.4G Mode dongle to a Bluetooth 5.0 dongle.

Software Changes:

▎ The HR2280-BT scanner need firmware HR22-BT_V1.01.010.EN or above. Kits coming with the new BT dongle will already have the firmware upgraded in the handheld device.

▎ The configuration file for the new dongle is Config_HR2081-BT_V1.3.EN. The Config of HR22-BT_V1.01.008.EN and below cannot be used.

BT 5.0 Dongle advantages:

▎ 50m transmission distance (direct line of sight in open air) against 30m for the previous 2.4G dongle.

▎ Better Bluetooth signal stability on the new Bluetooth 5.0 dongle.

Previous version   **New version**

Notes:

User manuals, 3D files, default parameters, packaging and warranty remain the same between HR2280-BT-SF and HR2280-BTV2-SF. In case of a dongle replace, devices with firmware lower than HR22-BT_V1.01.010.EN can be upgraded via Easyset to be compliant with the new Bluetooth 5.0 dongle.

If you have any questions or concerns regarding these changes, please let us know.

| **Hans Chen** | **David Craggs** | **Johan Vetsuypens** |
| VP Product Management | Growth Product Manager EMEA | Product Manager Scanning EMEA |